General Environmental Incident Summary

Incident: 4101 Date/Time Notice: 5/19/2016 1322 DEM Incident No:

Responsible Party: Sterling Construction Management

Date Incident: 5/16/2016 Time Incident: 1530 Duration: 1 minutes

County: Dunn **Twp:** 147 **Rng:** 96 **Sec:** 7 **Qtr: Lat:** 47.56070 **Long:** -102.96990 **Method:** Navigation quality GPS

Location Description: ONEOK Bear Creek NGL Pipeline (currently under construction). From 11th

Ave NW travel west on 7th Street approximately 5.0 miles (turns to 113th Ave

NW). Right of Way is north of the road.

Submitted By: Todd Kelvington Affiliation: ONEOK

Address: 100 West 5th Street

City: Tulsa State: OK Zip:

Received By:

Contact Person: Derrick Ingle

10020 HWY 200 East Dunn Center, ND

Distance Nearest Occupied Building: 0.75 Miles Release Contained: Yes

Type of Incident: Construction equipment failure

Description of Released Contaminant: Hydraulic Fluid

Volume Spilled: 0.25 gallons Aq Related: No

EPA Extremely Hazardous Substance: No Reported to NRC: Unknown

Cause of Incident:

Construction equipment hydraulic line failure

Risk Evaluation:

None. Immediate action occurred.

of Fatalities: 0 # of Injuries: 0 Affected Medium: 03 - soil

Potential Environmental Impacts:

Not Likely. Spill kit immediately deployed and impacted soils have been removed.

Action Taken or Planned:

Spill kit was immediately deployed. Impacted spill materials and surface soils were immediately bagged for disposal.

Wastes Disposal Location: Total Control is under contract to retrieve impacted wastes from the

Sterling Construction yard.

Agencies Involved:

Updates

Date: 6/2/2016 **Status:** Reviewed - Follow-up Required **Author:** Crowdus, Kory

Updated Volume:

Notes:

Release at a non-exempt E&P facility. Follow-up is required.

Date: 6/3/2016 Status: Correspondence Author: Suess, Bill

Updated Volume:

Notes:

Arranged with rep that follow-up will coincide with quarterly inspections.